



DUT command USB port is not C-compliant - CC pins are used to test the DUT's CC lines
Power input port signals dumb sink mode at 5V with 5.1kOhm pulldowns
120R termination meant as overstress test for buffers - use with non-buffered boards might result in damage or 'fail' result when testing.

